

Pohle, David

From: Pohle, David
Sent: Tuesday, February 16, 2016 12:37 PM
To: Montella, Daniel; Balla, Richard
Cc: Modigliani, Justine; Mann, Katherine; Metivier, Steven V LRB; Crawford, Margaret A LRB; Brown, Bridget LRB; Smith, Aaron C LRB
Subject: Remote sensing reconnaissance inspection of Martville Mine logging site and its vicinity
Attachments: Martville Mine Sept 11 2015.jpg

Today I completed a remote sensing reconnaissance inspection of the proposed gravel mine location at 13181 Sanford Road, Martville, Town of Sterling, Cayuga County, NY, using the most recent aerial image on the public Digital Globe website (attached). This image is dated September 11, 2015. The image depicts the area of logging and the creek and wetlands alongside the creek. In this image, the logging area appears fully vegetated with grass. The forest on the hillslopes surrounding the logged area appear intact. There is no visible indication of dredged or fill material or landclearing or sediment run-off in or around the creek or wetlands in the vicinity of the logged location.